

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,
T. 40 N., R. 70 E., MDM, NEVADA

CHAINS	
34.20	Fence, parallels railroad track.
40.33	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. T40N R70E $\frac{1}{4}$ S 17 S 16 1987 Set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the stainless steel post. From this corner, a steel fence post, exposed 24 ins. above ground, bears N. $68^{\circ} 22'$ E., 0.13 chs. dist.
42.50	Loray Wash, 50 lks. wide, 6 ft. deep, drains ENE.
47.00	Ridge, bears E. and W.
50.90	Fence, bears E. and W., enter meadow.
62.00	Thousand Springs Creek, 20 lks. wide, 2 ft. deep, course E.
75.00	Fence, bears E. and W., leave meadow.
80.66	The cor. of secs. 8, 9, 16 and 17, monumented with the decayed remains of a wooden post, firmly set alongside a steel fence post, with illegible scribe marks visible. At the corner point Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. T40N R70E S 8 S 9 S 17 S 16 1987 Reset the original wooden post and steel fence post, $5\frac{1}{2}$ ft. long, alongside the stainless steel post. S. $88^{\circ} 52'$ E., bet. secs. 9 and 16. Over rolling land, through scattered greasewood and native grass.
18.30	Trail road, bears NE. and SW.
19.20	Thousand Springs Creek, 20 lks. wide, 2 ft. deep, course NE.
39.41	Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.