

SURVEY OF THE SUBDIVISION OF SECTION 33,
T. 41 N., R. 54 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	SURVEY OF THE SUBDIVISION OF SECTION 33, T. 41 N., R. 54 E., MOUNT DIABLO MERIDIAN, NEVADA
	The normal subdivision of sec. 33 was not possible as a large mine tailing pond covers the majority of the section. The bearings and distances of the E-W and N-S center lines were calculated utilizing mean bearings to determine the positions of the C-N 1/16 and the C-E 1/16 sec. cors. which controls the NE 1/16 sec. cor. From the N 1/16 sec. cor. of secs. 33 and 34, on the E. bdy. of the sec. N. 89°24' W., on the E. and W. center line of the NE ¼ of sec. 33. Over nearly level land. 20.14 The NE 1/16 sec. cor. of sec. 33, monumented with an aluminum post, 2½ ins. diam., firmly set, projecting 8 ins. above the ground, with an aluminum cap mkd. T41N R54E NE 1/16 S 33 LS4643 1988 This monument is accepted as a careful and faithful determination of the position of the corner. This monument meets the standards of the BLM and was not remonumented. Add the marks BLM 1991 to the aluminum cap. From this same corner, the N. edge of a tailing pond bears S. 0°21' E., 14.80 chs. dist., the edge of the pond bears WNW. and ESE.