

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
T. 16 N., R. 21 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	
35.155	Intersect line 8-9, unpatented Lot No. 51, Block 8, Range D, Gold Hill Townsite, at a point from which Angle Point No. 9, hereinafter described, bears N. 58°23'40" W., 1.693 chs. dist.
40.393	The 1/4 sec. cor. of secs. 5 and 6, reestablished by John S. Parrish, Nevada Professional Land Surveyor No. 9475, in 2012, monumented with a rebar, 5/8 in. diam., 18 ins. long, firmly set, flush in a collar of stone, with aluminum cap mkd. T16N R21E 1/4 S6 S5 PLS9475 2011, as recorded in Storey County, Nevada, File No. 116315, and is accepted as a careful and faithful reestablishment of the position of the original corner. At the corner point Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, over a plastic-encased magnet, and in a collar of stone, with brass cap mkd. T16N R21E 1/4 S 6 S 5 2014 Insert the rebar inside the stainless steel post. From this corner, the cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp., bears N. 1°13'30" W., 40.393 chs. dist., monumented with a stainless steel post, 2 1/2 ins. diam., firmly set, projecting 2 ins. above an embedded mound of stone, 5 ft. diam., with brass cap mkd. as described in the field notes of the dependent resurvey of a portion of the subdivisional lines, T. 17 N., R. 21 E., executed under Group No. 736. From this cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp., Triangulation station "WHEELER MONUMENT RESET" bears N. 23°10'10" E., 44.088 chs. dist., monumented with a standard disk mkd. WHEELER MONUMENT 1897 1951, firmly set in the top of a concrete pier projecting 4 1/2 ft. above the ground. DEPENDENT RESURVEY OF A PORTION OF MINERAL SURVEY NO. 42, T. 16 N., R. 21 E., MOUNT DIABLO MERIDIAN, NEVADA Reestablishment of a Portion of the Survey Executed by U.S. Deputy Mineral Surveyor J.F. Kidder in 1868 Front Lode Consolidated claim on the Middle lode From the point for the post used as the point of commencement, determined by grant boundary adjustment between the cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp., and the 1/4 sec. cor. of secs. 5 and 6; there is no remaining evidence of the original corner.