

8th Standard Parallel N. through R. 57 E

T cor. as per field notes at 38⁰⁰ chs.; and ran N. of it; finding cor. stone, with monument of rock to W., lying loose upon the ground, apparently broken or decayed, with, of its marks, 6 notches on one side, alone legible. Fully identified it by distance from spring, gulch, and hill W.; as described in field notes.

Missing $\frac{1}{4}$ cor. on standard, which we ^{had} searched for. when running line bet. Secs. 5 & 6, 2 run E. for S. Cor. bet. Secs. 31 & 32; and found it, in fair condition, at 79⁰⁰; with rock mound, E of cor., in poor order. This we rebuilt, 3 ft. base, 3 ft. high, on old site. Finding no trace of $\frac{1}{4}$ cor. after a diligent and protracted search, set. new $\frac{1}{4}$ cor. with substantial monument; but afterwards accidentally stumbled on to old cor., very probably much out of line; but not being instructed to retrace for alignment, destroyed our cor.. Country very difficult on this line, (mine), at its intersection, by line