

Fractional W. bdy., T 28 N, R 23 E.

Chains

Land, somewhat rolling with a slope to the N.W.
Soil, dry, gravelly and stony. 3rd. rate. Poor feed of
sagebrush, with some grass and weeds, no timber.

N. bet. secs. 1 and 6.

Over somewhat rolling land, with a slope to the N.W.

40.00

50 ft. below sec. cor.

Set an iron post, 3 ft. long, 1 in. dia., 24 in. in the
ground for $\frac{1}{4}$ sec. cor. with brass cap mkd.

$\frac{1}{4}$
S 1 | S 6
1916

and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high W.
of cor.

80.00

25 ft. below $\frac{1}{4}$ sec. cor.

Set an iron post, 3 ft. long, 3 ins. dia., 24 ins. in the
ground for cor. of Tps. 28 and 29 N, Rgs. 22 and 23 E,
with brass cap mkd.

T 29 N
R 22 E | R 23 E
S 36 | S 31

S 1 | S 6
T 28 N
1916

and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high S.
of cor.

Land, somewhat rolling, with a slope to the N.W.

Soil, dry, gravelly and rocky. 2nd. and 3rd. rate. Poor
feed of sagebrush, with some grass and weeds. No timber.

stark

N. bdy. T 28 N, R 23 E.

From the cor. of Tps. 28 and 29 N, Rgs. 22 and 23 E,
E. bet. secs. 6 and 31.

Over somewhat rolling land, with a slope to the N.W.

40.00

25 ft. above Tp. cor.

Set an iron post, 3 ft. long, 1 in. dia., 24 ins. in the
ground for $\frac{1}{4}$ sec. cor. with brass cap mkd.

S 31

S 6
1916

stark