

COMPLETING SUBDIVISION OF T.44 N., R.32 E.

Chains

and verify the meridional indications at frequent intervals throughout the survey.

DEPENDENT RESURVEY PART OF
SOUTH BOUNDARY OF T.44 N., R.32 E.

REESTABLISHMENT OF THE SURVEYS EXECUTED BY SKINNER,
GARSIDE AND PREBLE, U.S. DEPUTY SURVEYORS, IN 1873.

Random Lines.

Beginning at the cor. of Tps. 43 and 44 N., Rs. 31 and 32 E., hereinafter described.

East, bet. secs. 6 and 31, on S. bdy. of Tp.

38.18 After diligent search, no trace could be found of the $\frac{1}{4}$ sec. cor.

78.18 After diligent search, no trace could be found of the cor. of secs. 5, 6, 31 and 32 on S. bdy. of Tp.

East, along the S. bdy. of the Tp., with continuous measurement, diligently searching for original $\frac{1}{4}$ sec. and sec. cors. at regular intervals.

238.00 Fall 3.53 chs. N. of the cor. of secs. 3, 4, 33 and 34, hereinafter described.

This line bears N.89°09'W., and the length is 238.00 chs.

Proportionate length of W. half mile bet. secs. 6 and 31 is 38.15 chs. and proportionate length of remaining half miles is 39.97 chs.

From the cor. of secs. 3, 4, 33 and 34, hereinafter described.

East, bet. secs. 3 and 34.

40.00 After diligent search, no trace could be found of the $\frac{1}{4}$ sec. cor.

73.22 Fall 149 lks. S. of the cor. of secs. 2, 3, 34 and 35, hereinafter described.

This mile bears S.88°50'W., and the length is 73.24 chs.

From the cor. of secs. 2, 3, 34 and 35, hereinafter described.

East, bet. secs. 2 and 35.

41.61 Fall 104 lks. N. of the $\frac{1}{4}$ sec. cor., hereinafter described.

This half mile bears N.88°34'W., and the length is 41.62 chs.