

445

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
TOWNSHIP 40 NORTH, RANGE 65 EAST, MDM, NEVADA

CHAINS	
	Reestablishment of a Portion of the Survey Executed by A. J. Hatch and J. H. Eaton, U.S. Deputy Surveyors, in 1870, and a Portion of the Resurvey and Survey Executed by H. Fitzhugh, U.S. Deputy Surveyor, in 1894
	From the cor. of secs. 35 and 36, monumented with an aluminum post, 2½ ins. diam., firmly set and exposed 6 ins. above ground, with aluminum cap mkd. as described in the field notes of T. 39 N., R. 66 E., executed under Group No. 582.
	N. 88° 44' W., on the S. bdy. of sec. 35.
	Over nearly level reseeded land, through scattered sagebrush and crested wheatgrass.
3.00	Trail road, bears NNW. and SSE.
32.65	The closing cor. of secs. 1 and 2, T. 39 N., R. 65 E., monumented with a redwood post, 3 ins. square, 36 ins. long, with illegible scribe marks visible, loosely set in a mound of earth, bears SOUTH, 0.06 chs. dist.
39.16	The ¼ sec. cor. of sec. 35, monumented with a redwood post, 3 ins. square, 36 ins. long, with illegible scribe marks visible, firmly set alongside a steel fence post.
	At the corner point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T40N R65E ¼ S 35 T39N R65E
	1989
	Reset the original wooden post and steel fence post, 5½ ft. long, alongside the stainless steel post.
	From this corner, a well casing, 6 ins. diam., bears N. 81° 44' W., 11.36 chs. dist.
	N. 88° 48' W., beginning new measurement.
	Over nearly level land.
4.00	Trail road, bears NNE. and SSW.
40.72	The cor. of secs. 34 and 35, monumented with the decayed remains of a juniper post in pieces, with illegible scribe marks visible, loosely set alongside a steel fence post.