

SURVEY No. 3760.

3

INSTRUMENT.

This survey was made with an A. Lietz Light, Mountain and Mining Transit. The courses were deflected from the true meridian as determined by direct solar observation. The distances were measured with 50 ft. and 500 ft. steel tapes.

REPORT.

The lode line of the location of this claim was run directly upon the ground and the several corners established by means of offsets from the lode line. All tie lines were run directly upon the ground.

The S.E. Cor. of Section 8 T.16 N.R., 21 E. M.D. B. and M. is marked by a porphyry stone 26 x 8 x 7 inches chiseled with four notches on the East and South faces. This is the nearest standing corner of the public survey which could be found and identified.

Survey No. 86. Hartford Lode.

CORs. Nos. 3 and 4 of this survey are in place. Cor. No. 3 is marked by a pine post 6 ins. square, showing 4 ft. above the ground. Markings nearly obliterated.

Cor. No. 4 was marked by ~~xxxx~~ a monument and a post 6 ins. square, 4 ft. long, lying along side, having rotted off. Name of lode legible, other markings obliterated. I set a pine post $4\frac{1}{2}$ ft. long, 4 ins. square in the center of the monument, scribed, 1-3760 ~~xxxx~~ Olympia, also 4-86, Hartford, to mark the corner. Line 3-4 is S. 33° 38'E. 1394.60 ft. instead of S. 34°E 1400 ft. as approved.

I found a monument, reported by some surveyors to be the $\frac{1}{4}$ Corner on the North Boundary of Sec. 8, no markings by which it can be identified, which bears from Cor. No. 1, this survey, $\angle$ N. 9° 18'E 1766.95 ft.

.....

U.S. Mineral Surveyor.