

438

Resurvey T. T. N. R. 27 E.

chains. Rgs. 26 and 27 E. 56 lks. N.

June 26.

While this line is within limits in alignment and measurement some corners are entirely obliterated and all in bad repair.

I therefore resurvey the line as follows;—

At the cor. to Tps. 6 and 7 N. Rgs. 26 and 27 E. which is a post vine square, marked as described by Surveyor General.

June 26.

At 7 A.M. l.m.t. I set off $23^{\circ}22'5''$ on the decl. arc, $38^{\circ}26'$ on the lat. arc, and determine a true meridian.

Thence I run $N. 89^{\circ}46' E.$ on a true line bet sec. 6 and 31, Old Carson and Purora, road bears N. N. and S. E.

Set a volcanic stone $12 \times 10 \times 8$ ins., 16 ins. in the ground

14.57

36.26