

Resurvey S. ldy T. 29 N.R. 29 E.
 Chain. S. 89° 52' E. on a true line
 on S. ldy. sec. 36.

Over mountainous land.
 ascending N. slope.

40.10 Intersect $\frac{1}{4}$ sec. cor. on S.
 ldy. sec. 36. a basalt stone
 8x8x10 ins. at on ground
 properly mkd. I rebuilt
 mound of stone N. of cor.

Too impracticable

✓ S. 89° 53' E. from $\frac{1}{4}$ sec. cor
 ascending N. slope

65.08 Ridge below NW and SW descent.

80.08 Intersect the cor. Tps. 28 and 29
 N. Rgs. 29 and 30 E. a lava
 stone 10x12x18 ins. at on ground
 mkd. with 6 notches on each edge
 and 29 E. on N.W.

28 N. on S.W.

29 N. on N.E. and

30 E. on S.E. face

I rebuilt mound of stone 3
 ft. base 2 ft. high S. of cor.

Land mountainous

Soil rocky 4th rate.

Sage brush and bunch grass.

Mountainous land 80.08 chs.

Aug. 26 1905.