

SOUTH BOUNDARY OF T.4 N., R.49½ E.

CHAINS

Mountainous land on 80.00 chs.

West, on S. bdy. of sec. 34.

Descend over rocky and mountainous land, through scattering cedar and pinon timber.

26.50 Intersect E. bdy. of T.4 N., R.49 E., 27.89 chs. South of the cor. of secs. 25-30-31 and 36, which is a basalt stone, 9x8x6 ins. above ground, marked and witnessed as described by the surveyor general.

Set a sandstone, 24x24x6 ins., 18 ins. in the ground, for closing cor. of Tps. 3 and 4 N., R.49½ E., marked C C 49½ on E., 3 N on S., and 4 N on N., with 6 grooves on N., S. and E. faces, and raise a mound of stone, 2 ft. base, 1½ ft. high, E. of cor.

Pits impracticable.

I destroy all marks on the cor. of secs. 25-30-31 and 36, that pertain to R.49½ E.

Land, mountainous.

Soil, rocky, 3rd. rate.

Timber, scattering cedar and pinon.

Mountainous land on 26.50 chs.

Connection line, mountainous, 27.89 chs.

May 23, 1907.