

Surveys and resurveys in T18N. R29E

chains

as follows:

Set an iron post 3 ft. long, 1 in. diam. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. with brass cap mkt.

$$\begin{array}{r} 533 \frac{1}{4} \\ \hline 54 \\ 1912 \end{array} \checkmark$$

dig pits 18x18x12 ins. E. and W. of post 3 ft. dist. and raise a mound of earth 3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high N. of cor.

The house of L. L. Downo bears N 50.55 E 22.50 chs. dist.

A barn bears N 32. E 19.70 chs. dist.

67.60 Fence, bears N. E. and S. W.; leave field.

67.90 Irrigating ditch, runs S. W.

68.00 Enter pasture land.

80.20 The cor. of secs. 4, 5, 32 and 33.

I destroy all traces of this corner and re-establish it at the same point as follows:

Set an iron post, close to and on E. side of fence which bears N. and S.; 3 ft. long. 3 ins. diam. 24 ins. in the ground for cor. of secs. 4, 5, 32 and 33, with brass cap mkt.

$$\begin{array}{r} T18N R29E \\ 532 \quad 533 \\ \hline 55 \quad 54 \\ T17N R29E \\ 1912 \end{array} \checkmark$$

dig pits 18x18x12 ins. in each sec.

5 $\frac{1}{2}$ ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high W. of cor. Land, level.

Soil, sandy loam. Good quality.

Cultivated fields and pasture land General southerly slope

June 17, 1912.