

Independent Resurvey of the Third Standard Parallel North
through Range 51 East.

Chains

80.00 Desc. 975 ft. over a broken W slope to,
On a W slope,
Set an iron post, 3 ft. long and 2 ins. in dia. 26 ins.
in the ground and in a mound of stone for the stan-
dard corner of secs. 31 and 32, with a brass cap
marked:

SC	
T16N	R51E
S31	S32

1925

From which,

A pinon, 5 ins. in dia. bears N 35° 00' E, 119
lks. dist., marked: T16NR51ES32SCBT.

A pinon, 3 ins. in dia. bears N 56° 00' W. 125
lks. dist., marked: 'SCBT' only.

No trace of the old standard corner found.

Land, rugged and broken mountains, general N exposure
and drainage.

Soil, rocky, 4th rate.

Timber pinon and juniper.

Undergrowth, sagebrush and mountain rush.

Poor grazing.

West on the S bdy. of sec. 31.

Over rolling hills, through scattering timber and
scant undergrowth, desc. 455 ft. over a W slope to,

33.30 Nine Mile draw, drains NW, asc. 210 ft. along a NE slope

40.00 On a N slope,

Set an iron post, 3 ft. long and 1 in. in dia. 4 ins.
in the ground and in a mound of stone for the stan-
dard $\frac{1}{4}$ sec. cor. of sec. 31, with a brass cap
marked:

SC
$\frac{1}{4}$ S31

1925

From which,

A pinon, 3 ins. in dia. bears N 70° 45' W, 63 lks.