

Dependent Resurvey of the East Boundary of T. 6 S., R. 38 E.

Chains

A pinon, 24 ins. diameter, bears S. 43° 30' E., 49 lks. dist., mkd. $\frac{1}{4}$ S30BT.

39.50

Set an iron post, 3 ft. long, 1 in. diameter, 16 ins. in the ground to solid rock, and in a mound of stone, for wit. $\frac{1}{4}$ sec. cor. of sec. 25 only, with brass cap mkd:

$\frac{1}{4}$ S25

WC

1933

from which

A pinon, 7 ins. diameter, bears N. 17° 45' W., 61 lks. dist., mkd. WC $\frac{1}{4}$ S25BT.

No other suitable tree available for marking.

Cor. is located on ridge bearing N. 30° E. and S. 30° W.

Desc. along a steep E. slope.

40.00

Point for $\frac{1}{4}$ sec. cor. of sec. 25, falls on steeply sloping bedrock where the monument cannot be established.

Continue along an E. slope.

43.00

Ridge, bears NW. and SE.; desc. 230 ft. along a SW. slope.

68.10

Head of a draw draining N. 60° W.; asc. 260 ft. along a rocky N. slope.

80.00

Set an iron post, 3 ft. long, 2 ins. diameter, 30 ins. in the ground, for cor. of secs. 25 and 36, with brass cap mkd:

T6S

R38E R39E

S25

S36

1933

from which

A pinon, 3 ins. diameter, bears S. 34° 45' W., 96 lks. dist., mkd. BT.

A pinon, 3 ins. diameter, bears N. 69° 30' W., 26 lks. dist., mkd. BT.

Land, rough mountains; general NW. drainage.

Soil, shallow gravelly to rocky loam, 3rd rate.

Timber; pinon and juniper; undergrowth, sagebrush and buckbrush.

Grazing, fair.

Survey of the East Boundary of T. 6 S., R. 38 E.

South, on true line, along the east boundary of sec. 36.

Over mountainous land, through scattering timber and a scant undergrowth; asc. 160 ft. over a steep N. slope.

8.90

Ridge, bears NE. and SW.; desc. 690 ft. along a rocky SW. slope.

36.90

Small draw, drains SW.; asc. 20 ft. along a NW. slope.