

Independent Resurvey of a Portion of the Subdivision, T. 4 N., R. 67 E.

Chains	from which A juniper, 4 ins. diam., bears N. 4° 15' E., 64 lks. dist., mkd. ¼ S20 BT. A juniper, 8 ins. diam., bears S. 24° E., 92 lks. dist., mkd. ¼ S29 BT.
44.90	Road, dirt, bears N. and S.
52.00	Wash, 30 lks. wide, 3 ft. deep, drains SW.
59.00	Road, dirt, bears NE. and SW.
79.98	The cor. of secs. 19, 20, 29 and 30. Land, nearly level, general SW. drainage. Soil, sandy loam. Timber, scattered juniper. Undergrowth, sagebrush.
	West, bet. secs. 19 and 30. Over nearly level land, through scattered timber.
9.60	Wash, 10 lks. wide, 2 ft. deep, drains SW.
35.50	Wash, 10 lks. wide, 1 ft. deep, drains SW.
40.00	Point for the ¼ sec. cor. of secs. 19 and 30. Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. T4N R67E ¼ $\frac{S19}{S30}$ 1957
	from which A juniper, 18 ins. diam., bears S. 2° W., 44 lks. dist., mkd. ¼ S30 BT. A juniper, 26 ins. diam., bears N. 11° W., 128 lks. dist., mkd. ¼ S19 BT.
71.69	Intersect the E. bdy., T. 4 N., R. 66 E. Point for the closing cor. of secs. 19 and 30. Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. T4N R67E $\frac{S19}{S30}$ C 1957 Deposit broken glass alongside iron post. No suitable bearing trees within limits. From this closing cor., the cor. of secs. 24 and 25, T. 4 N., R. 66 E., hereinbefore described, bears N. 0° 36' E., 1.60 chs. dist.